



Rec Inspect, LLC

## General

**StockNumber**

2302140P

**TypeCode**

FW

**Vin Number**

4YDFMOT2XP4700748

CW Auctions - Breaux Bridge, LA

**2310 N Frontage Rd  
Breaux Bridge, LA  
70517  
United States**

**ModelYear**

2023

**Make**

KEYSTONE

**Model**

Montana

**Interior Smell**

Clean

**Trim**

3763BP

**Received Date:**

Wednesday, October 16, 2024

**Overall picture of unit, should be from Front  
Right Corner**



**Seller:**

Camping World HPA

**Inspector:**

Ktrower

**Work Order:**

0001182

**Exterior Color**

White

**Interior Color**


White

Towable

Picture of VIN number, model number, and miles if motorized

DATE: 11/7/2022

MANUFACT



V.I.N.: 4YDFM0T2XP4700748

TYPE TRAILER

UNLOADED VEHICLE WEIGHT

GVWR

GAWR (EACH AXLE)

TIRE

RIMS

COLD INFL. PRESS

6559 KG / 144

7702 KG / 169

3175 KG / 700

ST235/80R16C

16x6

758 KPA / 110

THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY S

DATE OF MANUFACTURE SHOWN ABOVE.

ALL WEIGHTS ARE APPROXIMATE.

CARGO-CARRYING CAPACITY: 1116 KG / 2460 LB

CALCULATED WITH THE PROPANE TANKS FULL

AND ALL OTHER TANKS EMPTY

CAPACITIES

COLD: 203 KG      HOT: 60 KG

145 LB      132 LB



---

## Mechanical:

AC Hookup - 50 AMP  
A/C  
AM/FM Radio  
Awning - Power  
Beds  
Blinds/Curtains  
Cable Inlet  
Dining Table Seats

Entry Step - Manual  
External Hookups  
Ladder  
Microwave  
Refrigerator  
Porch Light  
Propane Tank

Power Slide Outs  
Slide Out - Bedroom  
Slide Out - Kitchen  
Slide Out - LR  
Sofa/Couch  
Stereo System  
Stove- Propane  
Televator  
Toilet  
TVs  
USB Ports

# Roof:

Interior Leaks or Water Damage

Pass/Accetable

Sealant Condition

Fair

Roof Membrane

Pass/Accetable

Lap Sealant

Fair

Pictures of Roof











---

## **Tires and Wheels:**

Picture of each tire tread



















---

## **General RV Pictures**

Pictures of all 4 corners of RV









Pictures of any equipment on exterior (ie tv, generator)













Pictures of each room inside the unit.





















## **Damage Summary and Additional Photos:**

This report is confidential and is intended for the use of the client reference above. It is presented to the client in accordance with the terms and conditions of the agreement entered into between client and Rec Inspect, LLC. Rec Inspect, LLC shall have no liability to any third party for the contents of the report, or lack thereof.