

Rec Inspect, LLC

General

<u>StockNumber</u> <u>TypeCode</u>

<u>2397558P</u> <u>4EZFV4022M6049836</u>

Vin Number

CW Auctions - Breaux Bridge, LA

2310 N Frontage Rd Breaux Bridge, LA 70517 United States

ModelYear 2020

(877) 882-9815 <u>Make</u>

K-Z

<u>Model</u>

<u>Durango Gold</u>

<u>Clean</u> <u>Trim</u>

G366FBT

Received Date:

Saturday, November 9, 2024

<u>Overall picture of unit, should be from Front Right Corner</u>



<u>Camping World Temecula</u>

Inspector:

Zakary Parker

Work Order: 0001483

Exterior Color In

Interior Color

<u>White</u>

<u>Brown</u>

<u>Towable</u>

Picture of VIN number, model number, and miles if motorized



Mechanical:

AC Hookup - 50 AMP
A/C
A/C Units
Awning - Power
Beds
Blinds/Curtains
Dining Table Seats

Entry Step - Manual
External Shower
External Hookups
Fantastic Vent
Formica Counter Top
Kitchen Floor Vinyl
Ladder
Mattresses
Microwave
Refrigerator
Porch Light
Propane Tank

Power Jacks
Power Slide Outs
Side Walls Laminated
Slide Out -Bedroom
Slide Out - Kitchen
Slide Out - LR
Sofa/Couch
Solid Countertop
Stove- Propane
Toilet
TVS
USB Ports

Roof:

Interior Leaks or Water Damage

Pass/Accetable

Sealant Condition

Pass/Accetable


Pictures of Roof


Roof Membrane

Pass/Accetable

Lap Sealant


Pass/Accetable





Tires and Wheels:

Picture of each tire tread









General RV Pictures

Pictures of all 4 corners of RV














Pictures of each room inside the unit.











Damage Summary and Additional Photos:

Damage 1 Description:

Dent in drivers side trim

Damage 1 pictures



This report is confidential and is intended for the use of the client reference above. It is presented to the client in accordance with the terms and conditions of the agreement entered into between client and Rec Inspect, LLC. Rec Inspect, LLC shall have no liability to any third party for the contents of the report, or lack thereof.